



Typical views of existing conditions at the existing 48-inch diameter culvert (no evidence of erosion from scouring).