



Photo 1 - Moonlight Drive  
EXISTING CONDITION

Photograph Information

|               |                    |                    |                    |
|---------------|--------------------|--------------------|--------------------|
| Date:         | Decedmber 01, 2022 | Photo Location:    | 42° 36' 22.7747" N |
| Time:         | 10:10 PM           |                    | 71° 10' 44.1409" W |
| Focal Length: | 36 mm              | Distance to Entry: | 117 Feet           |
| Camera:       | Canon EOS Rebel T7 |                    |                    |

Figure 1  
PHOTO SIMULATIONS



Photo 1 - Moonlight Drive  
SIMULATED CONDITION - 18ft high sound barrier wall

Photograph Information

|               |                    |                    |                    |
|---------------|--------------------|--------------------|--------------------|
| Date:         | Decedmber 01, 2022 | Photo Location:    | 42° 36' 22.7747" N |
| Time:         | 10:10 PM           |                    | 71° 10' 44.1409" W |
| Focal Length: | 36 mm              | Distance to Entry: | 117 Feet           |
| Camera:       | Canon EOS Rebel T7 |                    |                    |