



Norse Environmental Services, Inc.
2100 Lakeview Avenue, Unit 3A
Dracut, MA 01826
Ph: (978) 649-9932
Website: www.norseenvironmental.com

June 1, 2024

Director of Conservation Commission
Mr. Robert Douglas
36 Bartlet Street
Andover, MA 01810

Re: 9 Bancroft Road
Andover, MA 01810

Mr. Douglas,

Per your request, Norse Environmental Services, Inc. performed a subsequent site visit on 5-6-24 to inspect the area downgradient of man-made pond. I performed several soil augers and noted the following soil profile: 0-14" 10 YR 2/2 and 14-22" 10 YR 4/6. These soils are indicative of an upland soil. I recorded the following vegetation: foxtail meadow (*Alopecurus pratensis*), common burdock (*Arctium minus*), ground ivy (*Glechoma hederacea*), dandelion (*Taraxacum officinale*), grass (*Fescue sp.*) and thistle (*Cirsium sp.*). These are all upland meadow species except for the foxtail meadow. Please see the photographs below:




Photograph: 5-6-24

Auger downgradient of
the man-made pond.

Soil Auger



Munsell Chart



The area downgradient of the pond has a predominance of upland plant species and soils. If you have any questions or concerns regarding the above information, please do not hesitate to contact me.

Sincerely,

Maureen Herald

Maureen Herald, PWS, CWS